



# SOLDERING TECHNIQUES & TIPS




tight fit



crystals expand



solder (red) enters by capillary action




solder diffused into the structure


## #1 fit

piece must be light tight

\*solder does not fill gaps



Wrong




right

## #3 flux


use flux to protect metal from oxidation  
reflux for each reheating

## #5 heat


THE HEAT OF THE METAL WILL MELT & FLOW THE SOLDER, NOT THE FLAME OF THE TORCH



too soft for concentrated heat  
can deposit soot particles on work



causes heavy deposits of cuprous & cupric oxides — this prevents all solder flow  
\*risk overheating sections



last inch should touch metal surfaces

## #2 cleaning



the join & solder must be clean  
NO-finger oils, tape, pickle, buffering compound, or pencil marks

## #4 solder placement

carefully place solder on the join

\*use just enough solder to fill the join, it takes less time to cut the right sized piece than to remove excess later

### Common Soldering Problems

PROBLEM	REASON	SOLUTION
Incomplete or unsoldered joint	Not enough heat; metal was dirty; no flux; prolonged heating	Avoid playing the flame directly on the solder.
Solder balls up	Metal or solder may be dirty	Reflux and try again.
Solder jumps to one side of joint	One side is hotter than the other	Keep the torch moving so all parts heat equally.
Solder spills out into a large puddle	Too much solder; too high a heat	Use smaller pieces of solder; level the heat as you approach the flow temperature.